



Insulation Compatibility

Date: Aug 20, 2021

Supersedes Date: Mar 24, 1989; Oct 6, 1994; Aug 30, 1999

Bulletin Number: #01

ICD continuously tests products that might come in contact with, or be installed in close proximity to, OPACI-COAT-300®.

Polyisocyanurate insulation products present a potential problem when mounted behind OPACI-COAT-300® coated glass. This “polyiso” insulation can produce potentially harmful gas vapors that may adversely affect OPACI-COAT-300® and may also adversely affect other glass coatings.

Polyisocyanurate insulation is NOT approved for use with OPACI-COAT-300®. Please be aware of this potential problem and provide this information to your customers. It is ultimately the responsibility of the glazier/installer to ensure *all* glazing components used in contact with, or in close proximity to, OPACI-COAT-300® are compatible and approved for use.

Please call ICD Technical Services, at (360) 546-2286, regarding any questions about the information provided in this bulletin.